DELPHION

Tracking No Active Trail

Salact **(>)**

Log Out Work Files Saved Searches

THE PERSON NAMED IN

The Delphion Integrated View

Tools: Add to Work File: Create new Work File

to my to the Me man from it , then

View: INPADOC | Jump to Top

Derwent Title:

Get Now: PDF | File History | Other choices

Go to: Derwent

Email this to a

Time 0

li

JP09312459A2: MANUFACTURE OF PRINTED CIRCUIT BOARD WITH Title: THROUGHHOLE

PCB manufacturing method - involves developing negatives by projecting visible laser light beam and exposing pattern on substrate through visible

laser light exposure type resist layer [Derwent Record]

JP Japan Country:

Kind:

TAKEZOE KOJI: Inventor:

KANSAI PAINT CO LTD Assignee:

News, Profiles, Stocks and More about this company

1997-12-02 / 1996-05-23 Published / Filed:

> Application Number:

JP1996000128654

TPC Code:

Advanced: G03F 7/26; H05K 3/06; H05K 3/42; Core: more..

IPC-7: G03F 7/26: H05K 3/06; H05K 3/42;

1996-05-23 JP1996000128654

Priority Number: Abstract:

PROBLEM TO BE SOLVED: To manufacture a printed circuit board which has no problems of production of dusts and a damaged surface of the printed circuit board at manufacturing, has no defect in throughholes and has fine printed circuit pattern.

SOLUTION: After positive resist ink is filled in a throughhole part of a printed circuit board having the throughhole part, ultraviolet radiation is applied for development to the surface of the printed circuit board to remove the undesired positive resist ink depositted on the surface of the printed circuit board other than its throughhole part thereby removing the undesired positive resist ink and a visible light laser sensing resist layer is formed on the printed circuit board, and a visible light laser beam is exposed onto the visible light laser sensing resist layer in a beam pattern way so as to develop the laver.

COPYRIGHT: (C)1997,JPO

None Family:

DERABS C98-074196 DERC98-074196 Other Abstract Info:

Abstract

PROBLEM TO BE SOLVED: To manufacture a printed circuit board which has no problems of production of dusts and a damaged surface of the printed circuit board at manufacturing, has no defect in through-holes and has fine printed circuit pattern.

SOLUTION: After positive resist ink is filled in a through-hole part of a printed circuit board having the through-hole part, ultraviolet radiation is applied for development to the surface of the printed circuit board to remove the undesired positive resist ink deposited on the surface of the printed circuit board other than its through-hole part thereby removing the undesired positive resist ink and a visible light laser sensing resist layer is formed on the printed circuit board, and a visible light laser beam is exposed onto the visible light laser sensing resist layer in a beam pattern way so as to develop the layer.